









Power Steering Pump

MITSUBISHI

HIC NO.	Vehicle	OEM NO.	Picture
SP-MT001	mitsubishi Storm L200 2.5L 4D56	MR374897 MR210173 MR333800	
SP-MT002	mitsubishi PS110 PS125 4D33 4D34	MC093701	
SP-MT003	mitsubishi Canter FE83 4D34 3.9L	MK383006	
SP-MT004	mitsubishi Carisma (1995-2003)	49110-0522R	
SP-MT005	mitsubishi Galant VIII (1996-2006)	MR244933 MR272750 MR333754 MR333800 MR403522 MR403523	

<p>SP-MT006</p>	<p> MITSUBISHI L200 III (1996-2006) MITSUBISHI Montero I (1982-1991) MITSUBISHI Pajero I (1989-1991) </p>	<p>MB501385</p>	
<p>SP-MT007</p>	<p> MITSUBISHI L400 </p>	<p>MR267505</p>	
<p>SP-MT008</p>	<p> MITSUBISHI L200 </p>	<p>MB351257</p>	
<p>SP-MT009</p>	<p> MITSUBISHI L400 1995-2002 </p>	<p>MR267505</p>	
<p>SP-MT010</p>	<p> MITSUBISHI Triton </p>	<p>MR992873T</p>	

SP-MT011	MITSUBISHI Triton	MR992873	
SP-MT012	MITSUBISHI L200 (2005-) MITSUBISHI Pajero Sport (2008-)	MR992871	
SP-MT013	MITSUBISHI L300 4D56	57100-43003	
SP-MT014	MITSUBISHI Pajero Sport 4D56 2.5L Diesel	MB501838	
SP-MT015	MITSUBISHI Lancer IX (2003-), MITSUBISHI Colt V (1991-1996), MITSUBISHI Lancer VI (1991-2000)	MN184075 MR197658 MR403656	

<p>SP-MT016</p>	<p>mitsubishi Trition L200 4G64 KA5T KB5T 08-</p>	<p>MR995025</p>	
<p>SP-MT017</p>	<p>MITSUBISHI L200 4M40 K77 K67</p>	<p>MR374895</p>	
<p>SP-MT018</p>	<p>MITSUBISHI Pajero Montero L200 V43 V44 4D56</p>	<p>MR112853 MR267660</p>	
<p>SP-MT019</p>	<p>MITSUBISHI PREECA</p>	<p>MR353475</p>	
<p>SP-MT020</p>	<p>MITSUBISHI Pajero Montero V73 V77</p>	<p>4450A158 4450A157</p>	