

| HIC NO.  | OEM NO.   | APPLICATION   | PICTURE   |
|----------|---|---|---|
| WP-TO001 | 16100-59085   | GP: PA646<br>GMB: GWT-48A<br>NPW: T-73                        |     |
| WP-TO002 | 16100-60090   | GMB: GWT-18A<br>NPW: T-46                                     |    |
| WP-TO003 | 16100-78010<br>16100-78011                                | GP: PA1011<br>GMB: GWT-126A<br>NPW: T-114<br>IMASAF: 331011/R |    |
| WP-TO004 | 16100-59175<br>16100-59176<br>16100-59265                 | DYNA BU-60,70,83(TOYO<br>ACE)                                 |   |
| WP-TO005 | 16100-59075<br>16100-59076<br>GMB: GWT-109A<br>NPW: T-29A | TOYOTA COASTER<br>BB-10,11(W/O COOLER)                        |  |
| WP-TO006 | 16100-00705   | TOYOTA 2J   |  |