












Power Steering Pump

HYUNDAI

HIC NO.	Vehicle	OEM NO.	Picture
SP-HY001	HYUNDAI Santa Fe 2001-2006	57100-2E100	
SP-HY002	HYUNDAI SONATA 2.4L 00-05	57100-38100	
SP-HY003	HYUNDAI Sonata 2.0 HYUNDAI ELANTRA	57100-3D001 57100-2D100	
SP-HY004	HYUNDAI ACCENT III 1.4/1.6	57100-1E000 57100-1G000	
SP-HY005	HYUNDAI ACCENT I 1.5I HYUNDAI ACCENT II 1.5/1.6 HYUNDAI COUPE 1.6/2.7 HYUNDAI ELANTRA 1.6	57100-2D050	
SP-HY006	HYUNDAI Solaris (2010-)	57100-4L000	

<p>SP-HY007</p>	<p>HYUNDAI TRAJET 2.0</p>	<p>57100-3A000</p>	
<p>SP-HY008</p>	<p>HYUNDAI Accent 2000-2002</p>	<p>57110-25000 57110-22502</p>	
<p>SP-HY009</p>	<p>HYUNDAI Sonata 2.7L 2002-2005 HYUNDAI Santa Fe 2.7L 2001-2006</p>	<p>57100-26100 57100-38500 57100-2C200</p>	
<p>SP-HY010</p>	<p>HYUNDAI Matrix FC 1.6 2001-2010</p>	<p>57110-17000 57100-17000</p>	
<p>SP-HY011</p>	<p>HYUNDAI H100</p>	<p>57100-4B010 57100-4B000</p>	

SP-HY012	HYUNDAI Santa Fe 2.4L 2001-2004	57100-26200	
SP-HY013	HYUNDAI H1 2001-2007	57100-4A010 57100-4A050 57100-4F100 57100-4A000	
SP-HY014	HYUNDAI	57100-5H101	
SP-HY015	HYUNDAI IX35 2010-2014 HYUNDAI SONATA 8	57100-2Z300	
SP-HY016	HYUNDAI Tuscon 2.0	57100-2E000	
SP-HY017	HYUNDAI Tucson G6BA 2005-2010 KIA Sportage G6BA 2005-2010	AAZ215449 21-5449 57100-2E100,	